XCSZ90

Telemecanique Safety switches XCS, padlocking device, for upto 3 padlocks, compatible with XCSA



Main

| Wilding | |
|---------------------------------------|-----------------------------------|
| Range of product | Telemecanique Safety switches XCS |
| Accessory / separate part categor | Locking accessories |
| Accessory / separate part type | Padlocking device |
| Accessory / separate part designation | Padlocking device |
| Accessory / separate part destination | For up to 3 padlocks |
| Product specific application | To prevent insertion of actuator |

Complementary

| o o mpromornary | | |
|-----------------------|----------|--|
| Product compatibility | XCSB | |
| | XCSC | |
| | XCSA | |
| | XCSE | |
| Net weight | 0.055 kg | |

Packing Units

| 3 - 3 | | |
|------------------------------|-----------|--|
| Unit Type of Package 1 | PCE | |
| Number of Units in Package 1 | 1 | |
| Package 1 Height | 10.000 cm | |
| Package 1 Width | 10.000 cm | |
| Package 1 Length | 2.500 cm | |
| Package 1 Weight | 37.000 g | |
| Unit Type of Package 2 | S01 | |
| Number of Units in Package 2 | 30 | |
| Package 2 Height | 15 cm | |
| Package 2 Width | 15 cm | |
| Package 2 Length | 40 cm | |
| Package 2 Weight | 1.289 kg | |
| | | |

Offer Sustainability

| Circularity Profile | € End of Life Information |
|--|---|
| California proposition 65 | WARNING: This product can expose you to chemicals including: Diisononyl phthalate (DINP), which is known to the State of California to cause cancer, and Di-isodecyl phthalate (DIDP), which is known to the State of California to cause birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov |
| For all Reach Rohs enquiries contact us at | sustainability@tesensors.com |

Contractual warranty

| | · · · · · · · · · · · · · · · · · · · |
|----------|---------------------------------------|
| Warranty | 18 months |
| | |