XMLZL004

Pressure sensors XM, fixing plate for replacing XMJA or XMGB pressure switch by XML pressure switch



Main

| Range of product | OsiSense XM | |
|---------------------------------------|--|--|
| Accessory / separate part categor | Mounting and fixing accessories | |
| Accessory / separate part destination | Electromechanical pressure switch Electromechanical vacuum switch | |

Complementary

| Accessory / separate part type | Plate | |
|--------------------------------|---------|--|
| Product compatibility | XMLC010 | |
| | XMLBM05 | |
| | XMLA500 | |
| | XMLAM01 | |
| | XMLD500 | |
| | XMLB010 | |
| | XMLA004 | |
| | XMLB500 | |
| | XMLCM05 | |
| | XMLA010 | |
| | XMLC500 | |
| | XMLD010 | |
| Net weight | 0.11 kg | |
| | | |

Packing Units

| 3 | | |
|------------------------------|----------|--|
| Unit Type of Package 1 | PCE | |
| Number of Units in Package 1 | 1 | |
| Package 1 Height | 1.0 cm | |
| Package 1 Width | 5.0 cm | |
| Package 1 Length | 6.0 cm | |
| Package 1 Weight | 105.0 g | |
| Unit Type of Package 2 | S01 | |
| Number of Units in Package 2 | 40 | |
| Package 2 Height | 15.0 cm | |
| Package 2 Width | 15.0 cm | |
| Package 2 Length | 40.0 cm | |
| Package 2 Weight | 4.409 kg | |
| | | |

Offer Sustainability

| California proposition 65 | WARNING: This product can expose you to chemicals including: Diisononyl phthalate (DINP), which is known to the State of California to cause cancer, and Di-isodecyl phthalate (DIDP), which is known to the State of California to cause birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov |
|--|---|
| For all Reach Rohs enquiries contact us at | sustainability@tesensors.com |

Contractual warranty

Warranty 18 months

